

Technical Bulletin

PRODUCT RECALL ADC0450

Due to a possible manufacturing issue that we have been made aware of, our braking reference, - ADC0450 may have a risk of fracturing where the top hat and disc face meet. This applies to all product with batch code TW, which can be found on the disc outer circumference or on the box product label.



We are taking the precautionary measure of recalling all product examples from the marketplace.

It is important that any stock of ADC0450 currently being held is returned to Comline, and request you cease selling this part number with immediate effect.

Please contact your Comline Sales Manager who will be able to arrange the return and subsequent credit of your stock.

Please see image below of ADC0450 label with batch code TW and disc edge marking:



Please see area highlighted in red displaying the manufacturing default on ADC0450:



We are working on the matter as a priority and will update once it is resolved. Should you have any further queries regarding ADC0450 please contact us on **01582 578 888** or alternatively contact our Product Team at **pdd@comline.uk.com**